Message

From: Jack Thorsen [jack@autumnwoodesh.com]

Sent: 3/19/2015 3:00:57 PM

To: Nordine, John [nordine.john@epa.gov]

CC: 'Robert Kay' [rtkay@usgs.gov]; Gerald Ruopp [gruopp@centralwire.com]

Subject: FW: Techalloy GP sites

Attachments: removed.txt

John:

Proposed sites are listed below:

Geoprobe Location	Latitude	Longitude
GP-25	42° 15.126′	88° 32.865'
GP-26	42° 15.138'	88° 32.881'

This is part of the revised Work Plan I am sending to Central Wire today.

Regards,

Jack

John W. Thorsen, P.E. Autumnwood ESH Consultants 262.237.1130

From: Nordine, John [mailto:nordine.john@epa.gov]

Sent: Thursday, March 19, 2015 7:07 AM

To: Jack Thorsen **Cc:** Bob Kay

Subject: Techalloy GP sites

Mr. Thorsen,

Mr. Kay plotted up the Geoprobe lat/longs you sent. Is the GP-24 information correct? His plot shows it pretty much due north of GP-23, it is further north and west than the map figure that was used to base my picks of the new locations shows it. Jack please double check the numbers and let EPA know if they are correct.

Also, can Autumwood send lat/longs for the proposed additional Geoprobe locations? The map locations are not informative and EPA would like to double check things. Depending on how things look, EPA may want to ask for altered GP locations.

Ya Maringo mari in Bappe. "In Yang birn inan mani, manni, ordatel Yalg birth ini pata it is marte and mala.	